

# Bags GCMI - PMS Conversion Chart

<b>GCMI 13</b> PMS YELL	<b>GCMI 10</b> PMS 115	<b>GCMI 103</b> PMS 116	<b>GCMI 81</b> ORNG 021	<b>GCMI 80</b> PMS 1655	<b>GCMI 82</b> PMS 165
<b>GCMI 74</b> PMS 186	<b>GCMI 76</b> PMS 1935	<b>GCMI 609</b> PMS 207	<b>GCMI 49</b> ORNG 253	<b>GCMI 39</b> PMS 288	<b>GCMI 31</b> PMS 293
<b>GCMI 387</b> PMS 640	<b>GCMI 3213</b> PMS 3282	<b>GCMI 21</b> PMS 356	<b>GCMI 24</b> PMS 3425	<b>GCMI 29</b> PMS 361	<b>GCMI 2081</b> PMS 368
<b>GCMI 50</b> PMS 1675	<b>GCMI 52</b> PMS 1817	<b>GCMI 523</b> BLACK 5	<b>GCMI 90</b> PROC BLK	<b>GCMI 91</b> WHITE	

Variations may occur

